




**Repair
Renew
Remanufacture**

50% OF ALL FAILURES IN WIND TURBINES ARE DUE TO ELECTRONIC FAILURES

Lost Days Per Year



Source: WEU Onshore Asset Optimization & Reliability Benchmarking Report 2015.
Data source: Sciemus.



PSI REPAIR SERVICES, INC.

© 2018 PSI Repair Services, Inc., is a subsidiary of Phillips Service Industries, Inc.

RSI-16-115 10/25/2018

United States
11900 Mayfield
Livonia, Michigan 48150-1710
(800) 325-4774

Canada—Ship to:
PSI Repair Services, Inc.
C/O WWD - Cole International Inc.
3950 Malden Road
Windsor, Ont. CN N9C 2G4
(800) 325-4774

Canada—Submit Payments to:
PSI Repair Services, Inc.
P.O. Box 21073
Windsor, Ont. CN N9B 3T4

psi-repair.com



ISO 9001:2008
CAGE CODE 5N884