



**Repair
Renew
Remanufacture**


MODEL 210521 DROP-IN DAUGHTER BOARD REPLACEMENTS FOR GE AEPG ON PITCH BATTERY CHARGERS

GE AEPG daughter boards, used to upgrade 20Nm and 30Nm Pitch Battery Chargers, help reduce the possibility of damage from voltage polarity reversal caused by a pitch battery at its end of life. Over time, these units experience a high rate of failure.

PSI now offers a Drop-in Daughter Board Replacement, model 210521, to improve battery charger reliability. From time-to-time, we may have these Drop-in Daughter Board Replacements in stock, but the maximum turnaround would be about 4 weeks.


NOTE: There are 12 battery charger cards in 1.5 – 77 through 1.6 – 82.5 generation turbines.

All 1.6/1.7 - 100 and 2.x MW units contain 18 charger cards.



**For more information:
Call 800-325-4774 or visit psi-repair.com**



psi-repair.com

 ISO 9001:2008
 CAGE CODE 5N884

United States
 11900 Mayfield
 Livonia, Michigan
 48150-1710
 (800) 325-4774

Canada—Ship to:
 PSI Repair Services Inc.
 C/O WWD - Kuehne & Nagel
 3950 Malden Road Unit #5
 Windsor, Ont. CN N9C 2G4

Canada—
Submit Payments to:
 PSI Repair Services, Inc.
 P.O. Box 21073
 Windsor, Ontario N9B 3T4



Europe
 Via Paolo Emilio, 34
 Roma RM 00192
 Italy
 +39 06 454 37023