




Repair
Renew
Remanufacture

UPGRADED, DROP-IN REPLACEMENTS FOR XANTREX® MATRIX INVERTERS FOUND IN GE 1.5MW S SERIES WIND TURBINES

**Does your wind farm use GE 1.5MW S Series turbines?
Do you have issues supporting the now obsolete Xantrex Matrix Inverters?**

Good News: PSI Repair Services, the leading independent service provider (ISP) in the wind energy industry, has introduced an upgraded, drop-in replacement for the Xantrex Matrix Inverter found in GE 1.5MW S Series turbines. The PSI replacement inverter is a form, fit and function solution with advanced fault detection and higher efficiency than the OEM design. As a result, you can supplement your current inventory with more reliable, longer-lasting technology and keep your turbines online, all while saving time and money.

If you are not interested in a replacement unit, PSI also repairs faulty Xantrex Matrix Inverters from GE 1.5MW S Series turbines with newer, more efficient parts, leading to improved performance and longer product life.



A blown Xantrex Matrix Inverter from a GE 1.5MW S Series wind turbine.



An upgraded replacement inverter from PSI Repair Services.

Need more peace-of-mind? Xantrex Matrix Inverters repaired and replaced by PSI have been rigorously field tested with successful results. Plus, PSI provides custom crating for all inverters to secure them from damage during shipping. Our inverter crates are also perfect for long term storage and return shipments of damaged cores. Give PSI a call today at 800-325-4774.

See reverse for benefits.

Start saving time and money today! Call us at 800.325.4774, or visit psi-repair.com.




Benefits of selecting PSI to repair or replace your broken Xantrex Matrix inverter:

1. Reduced repair/replacement cost
2. Reduced turnaround time
3. More reliable than OEM matrix inverter
4. Runs cooler than OEM matrix inverter
5. Improved, high-speed fault detection circuitry
6. Designed for longer life – estimated to be twice the life of the original design
7. Designed to work with newer generation IGBTs
8. Upgraded matrix inverters have passed rigorous field testing
9. Upgraded matrix inverters are corrosion protected
10. PSI provides custom crating for our upgraded matrix inverters to avoid damage during shipping, storage and core returns.

Start saving time and money today!

Call us at 800.325.4774, or visit psi-repair.com.



psi-repair.com



ISO 9001:2008
CAGE CODE 5N884

United States
11900 Mayfield
Livonia, Michigan
48150-1710
(800) 325-4774

Canada—Ship to:
PSI Repair Services Inc.
C/O WWD - Kuhne & Nagel
3950 Malden Road Unit #5
Windsor, Ont. CN N9C 2G4

**Canada—
Submit Payments to:**
PSI Repair Services, Inc.
P.O. Box 21073
Windsor, Ontario N9B 3T4



Europe
Via Paolo Emilio, 34
Roma RM 00192
Italy
+39 06 454 37023