



**PSI REPAIR SERVICES, INC.**

# GENERAL ELECTRIC WEPA CIRCUIT CARD


## MODEL NUMBERS:

IS215WEPAH2AB/IS210BPPBH2CAA  
IS215WEPAH2BA/IS210BPPCH1AC  
IS215WEPAH2BA/IS210BPPCH1ACA

IS215WEPAH2BA/IS210BPPCH1AD  
IS215WEPAH2BA/IS210BPPCH1AEC  
IS215WEPAH2BB/IS210BPPCH1AC

IS215WEPAH2BB/IS210BPPCH1AD  
IS215WEPAH2BPR1/IS210BPPCH1ACA

- PSI has repaired in excess of 500 of these WEPA boards.
  - This model receives a standard upgrade on commonly failed components.
  - Common failures include failed components, burnt boards and corrupted software.
  - Repair procedure includes initial visual inspection looking for damaged components, foil traces and connectors.
- We then test for internal shorts or opens. If all that looks good we power the board up and exercise the internal circuitry and verify network communications with associated boards.



[psi-repair.com](http://psi-repair.com)



ISO 9001:2008  
CAGE CODE 5N884

**United States**  
11900 Mayfield  
Livonia, Michigan  
48150-1710  
(800) 325-4774

**Canada—Ship to:**  
PSI Repair Services Inc.  
C/O WWD - Kuehne & Nagel  
3950 Malden Road Unit #5  
Windsor, Ont. CN N9C 2G4

**Canada—**  
**Submit Payments to:**  
PSI Repair Services, Inc.  
P.O. Box 21073  
Windsor, Ontario N9B 3T4



**Europe**  
Via Paolo Emilio, 34  
Roma RM 00192  
Italy  
+39 06 454 37023